

Hyundai/Kia

A4CF1, A4CF2

sonnax®

TIME TESTED • INDUSTRY TRUSTED®

1 Automatic Drive • P.O. Box 440 • Bellows Falls, VT 05101-0440 USA
(800) 843-2600 • (802) 463-9722 • F: (802) 463-4059 • www.sonnax.com

AKPPHELP.RU

Руководство по ремонту АКПП

1 84741-07K TCC Regulator Valve Kit

Helps cure:

- TCC apply/release problems
- Converter codes
- Loss of lube

2 84741-13K Oversized Damper Clutch Control Valve Kit

Helps cure:

- Converter apply/release issues
- Excess slip RPM
- Cycling TCC RPM

Note: Requires tool kit F-84741-TL13 & the VB-FIX reaming fixture.

3 84741-01K Boost Valve & Sleeve Kit

Helps cure:

- Insufficient line rise in drive ranges
- Higher-than-normal reverse pressures
- Soft shifts

4 84741-03K Oversized Pressure Regulator Valve Kit

Helps cure:

- High/Low line pressure
- Soft and/or harsh shifts
- Clutch failure

Note: Requires tool kit 84741-TL3.



5 84741-10K Oversized Pressure Reducing Valve Kit

Helps cure:

- Low line pressure
- No TCC apply
- Delayed forward

Note: Requires tool kit F-84741-TL10 & the VB-FIX reaming fixture.

6 84741-16K Oversized Pressure Control Valve Kit

Fits any of 3 locations

Helps cure:

- Burnt clutches/brakes
- Shift complaints

Note: Requires tool kit F-84741-TL16 & the VB-FIX reaming fixture.

Click on Sonnax part numbers to see more information.